

* : hyeontae@huchems.com
TEL:061-680-4654 FAX:061-680-4670

M/R						
RYM200501398	001	2005/09/28 <u>2005/10/31</u>	M13	M1361P105AB-001	EA	1
MAIN. S/P FOR 61-P-105A/B,AFTER SEPARATOR PUMP,M/D:H101-3.7E-1CASP,S/N C46-0906A-1,2,MAKER:NIKKISO CO.,LTD.						
****. BEARING,TAPE,P/N 02-032-4022B.						
RYM200501398	002	2005/09/28 <u>2005/10/31</u>	M13	M1361P105AB-004	EA	1
MAIN. S/P FOR 61-P-105A/B,AFTER SEPARATOR PUMP,M/D:H101-3.7E-1CASP,S/N C46-0906A-1,2,MAKER:NIKKISO CO.,LTD.						
****. GASKET,TEFLON,P/N 02-071-4019C.						
RYM200501398	003	2005/09/28 <u>2005/10/31</u>	M13	M1361P105AB-005	EA	3
MAIN. S/P FOR 61-P-105A/B,AFTER SEPARATOR PUMP,M/D:H101-3.7E-1CASP,S/N C46-0906A-1,2,MAKER:NIKKISO CO.,LTD.						
****. GASKET,TEFLON,P/N 02-071-4018C.						
*** LAST ITEM ***						
: 2005 10 11 16:00						

: