

\* : hyeontae@huchems.com  
TEL:061-680-4654 FAX:061-680-4670

M/R						
RYM200501029	001	2005/08/03	M07	M0700S-919	EA	2
MR200508030002		<u>2005/08/30</u>				
****. VALCO ROTOR SEAL FOR INJECTION VALVE,AUTOSAMPLER MIDAS 830,MIDAS CAT.#3796.043.						
RYM200501029	002	2005/08/03	M07	M0700S-920	EA	2
MR200508030002		<u>2005/08/30</u>				
****. VALCO LOOP 5 µ I WIH FITTINGS,AUTOSAMPLER MIDAS 830,MIDAS CAT.#3796.046.						
RYM200501029	003	2005/08/03	M07	M0700S-921	EA	2
MR200508030002		<u>2005/08/30</u>				
****. 250 µ I SYRINGE,AUTOSAMPLER MIDAS 830,MIDAS CAT.#4400.250 .						
RYM200501029	004	2005/08/03	M07	M0700S-922	EA	1
MR200508030002		<u>2005/08/30</u>				
****. PLUNGER REPLACEMENT TIP FOR 250 µ I SYRINGE,PK OF 10EA,AUTOSAMPLER MIDAS 830,MIDAS CAT.#0900.742.						
RYM200501029	005	2005/08/03	M07	M0700S-923	EA	1
MR200508030002		<u>2005/08/30</u>				
****. VALCO FERRULE,PK OF 10EA,AUTOSAMPLER MIDAS 830,MIDAS CAT.#0700.004 .						
RYM200501029	006	2005/08/03	M07	M0700S-924	EA	1
MR200508030002		<u>2005/08/30</u>				
****. VALCO NUT,PK OF 10EA,AUTOSAMPLER MIDAS 830,MIDAS CAT.#0700.005.						
*** LAST ITEM ***						
: 2005 08 08 16:00						

: