

휴켄스주식회사

* 담당자 : 김천수 cskim@huchems.com

TEL:061-680-4653 FAX:061-680-4539

견적의뢰서

Page 1 of 1

RYM200901898 - 1

RUN-DATE : 2009-12-14

RUN-TIME : 10:07:17오전

구매요구번호 M/R번호	품목번호	발행일자 입고요구일자	계정	자재번호	단위	구매요구량
RYM200901898 MR200912110004	001	2009/12/14 <u>2009/12/15</u>	M13	M1300YPMI-008	EA	5.0000
****. SLEEVE, SPACER COUPLING, CODE:06RE, MAT'L:EPDM, FOR COUPLING SC6, MFR.:영풍정밀펌프 OR EQUAL.						
RYM200901898 MR200912110004	002	2009/12/14 <u>2009/12/15</u>	M13	M1300YPMI-013	EA	2.0000
****. FLANGE, SPACER COUPLING, CODE:6SC35, MAT'L:DCI, FOR COUPLING SC6, MFR.:영풍정밀펌프 OR EQUAL.						
RYM200901898 MR200912110004	003	2009/12/14 <u>2009/12/15</u>	M13	M1300YPMI-014	EA	2.0000
****. FLANGE, SPACER COUPLING, CODE:7SC35, MAT'L:DCI, FOR COUPLING SC7, MFR.:영풍정밀펌프 OR EQUAL.						
RYM200901898 MR200912110004	004	2009/12/14 <u>2009/12/15</u>	M13	M1371P002AB-001	EA	5.0000
MAIN. S/P FOR 71-P-002A/B, 93% SULFURIC ACID FEED PUMP, PUMP SERIES & ALLOY:1.5 X 1-4/32 D20, S/N A:910277, B:910278, CAP.(GPM):4.4, TDH(FT):46, NPSHA(FT):0.5, RPM:3500, IMPELLER DIA.(BT-49720A):3-1/4", MAX.:4", MOTOR POWER:1HP, MFR.:YOUNG POONG(DURIRON CO., INC).						
****. GASKET, IMPELLER, MAT'L:TFR, I/N 104, FOR 71-P-004A/B, 006A/B, 007A/B, 009A/B.						
*** LAST ITEM ***						
견적서마감일 : 2009년 12월 15일 16:00시						

납품장소 : 여수공장 창고도