

* : shc@huchems.com
TEL:061-680-4652 FAX:061-680-4670

M/R						
RYM200701334	001	2007/11/29	M05	M0500UNION-011	EA	10
MR200711280002		<u>2007/12/10</u>				
****. UNION,M/D:SQH08-00,TUBE O.D.:8MM,UNION MAKER:()TPC OR EQUAL.						
RYM200701334	002	2007/11/29	M05	M0500UNION-012	EA	10
MR200711280002		<u>2007/12/10</u>				
****. UNION,M/D:SQH06-00,TUBE O.D.:6MM,UNION MAKER:()TPC OR EQUAL.						
RYM200701334	003	2007/11/29	M05	M0500UNION-013	EA	10
MR200711280002		<u>2007/12/10</u>				
****. UNION Y,M/D:SQH06-00,TUBE O.D.:6MM,UNION MAKER:()TPC OR EQUAL.						
RYM200701334	004	2007/11/29	M05	M0500UNION-014	EA	10
MR200711280002		<u>2007/12/10</u>				
****. REDUCER UNION Y,M/D:SQH06-08,TUBE O.D.:8MM/6MM,REDUCER UNION MAKER:()TPC OR EQUAL.						
RYM200701334	005	2007/11/29	M05	M0500UNION-015	EA	10
MR200711280002		<u>2007/12/10</u>				
****. BULKDE UNION,M/D:SQE08-00,TUBE O.D.:8MM BULKED UNION MAKER:()TPC OR EQUAL.						
*** LAST ITEM ***						
: 2007 12 10 16:00						

: