

* : cskim@huchems.com
TEL:061-680-4653 FAX:061-680-4539

M/R						
RYM200900733	001	2009/05/28	M05	M0564PSV106-001	SE	1.0000
MR200905270003		<u>2009/07/20</u>				
****. KIT, REPAIR, P/N:06.3366, FOR 4" X 6" TYPE 546 MAIN VALVE M/D:54612P46/S1, MAKER:ANDERSON GREENWOOD						
RYM200900733	002	2009/05/28	M05	M0564PSV106-002	EA	1.0000
MR200905270003		<u>2009/07/20</u>				
****. RING, RETAINING, P/N:05.1071, SPIROLOX RS-227, 302SST, FOR 4" X 6" TYPE 546 MAIN VALVE M/D:54612P46/S1, MAKER:ANDERSON GREENWOOD						
RYM200900733	003	2009/05/28	M05	M0564PSV106-003	EA	1.0000
MR200905270003		<u>2009/07/20</u>				
****. RING, WEDGE, P/N:02.7627, TEFLON-TEE W/25%, FOR 4" X 6" TYPE 546 MAIN VALVE M/D:54612P46/S1, MAKER:ANDERSON GREENWOOD						
RYM200900733	004	2009/05/28	M05	M0564PSV106-004	SE	2.0000
MR200905270003		<u>2009/07/20</u>				
****. KIT, REPAIR, P/N:04.4959, FOR PILOT VALVE M/D:500 PILOT OF 4" X 6" TYPE 546 MAIN VALVE(M/D:54612P46/S1), MAKER:ANDERSON GREENWOOD						
*** LAST ITEM ***						
: 2009 06 03 16:00						

: