

* : jh119@huchems.com
TEL:061-680-4652 FAX:061-680-4670

M/R						
RYM200500769	001	2005/06/09	M02	M0200PP-009	EA	20
MR200506070001		<u>2005/06/13</u>				
****. PLUG,2P,3W,125V,15A,CAT.NO.:CA-P5102,MAKER: , OR EQUAL.						
RYM200500769	002	2005/06/09	M02	M0200PP-027	EA	20
MR200506070001		<u>2005/06/13</u>				
****. PLUG,2P,15A,300V,"ㄇ",CAT.NO.:CA-P6151,MAKER: OR .						
RYM200500769	003	2005/06/09	M02	M0200RT-001	EA	20
MR200506070001		<u>2005/06/13</u>				
****. RECEPTACLE,2P,3W,MIN 125V,15A,DUPLEX FLUSH MOUNTING TYPE,MAKER: OR EQUAL.						
RYM200500769	004	2005/06/09	M02	M0200RT-002	EA	20
MR200506070001		<u>2005/06/13</u>				
****. RECEPTACLE,2P,3W,MIN 125V,15A,DUPLEX SURFACE MOUNTING TYPE,MAKER: .						
RYM200500769	005	2005/06/09	M02	M0200RT-020	EA	20
MR200506070001		<u>2005/06/13</u>				
****. RECEPTACLE,2P,15A,250V,CAT.NO.:CA-C6603,220V 2 (),MAKER: .						
RYM200500769	006	2005/06/09	M02	M0200RT-026	EA	20
MR200506070001		<u>2005/06/13</u>				
****. RECEPTACLE,2P,15A,250V, ,CAT.NO.:CA-C2603,MAKER: , OR .						
*** LAST ITEM ***						
: 2005 06 14 16:00						

: