

\* : cskim@huchems.com

TEL:061-680-4653 FAX:061-680-4539

M/R						
RYM201000317	001	2010/03/19	M02	M0200BK-116	EA	6.0000
MR201003180006		<u>2010/03/25</u>				
****. BREAKER,EBS 33b.460V 30A. :AC460V 5KA.3 3W.3P3E.						
:100MA.MAKER:LS OR EQUAL						
RYM201000317	002	2010/03/19	M02	M0200BK-117	EA	4.0000
MR201003180006		<u>2010/03/25</u>				
****. BREAKER,EBS 103b.460V 60A. :AC460V 25KA.3 3W.3P3E.						
:100MA.MAKER:LS OR EQUAL						
RYM201000317	003	2010/03/19	M02	M0200BK-118	EA	4.0000
MR201003180006		<u>2010/03/25</u>				
****. BREAKER,EBS 103b.460V 100A. :AC460V 25KA.3 3W.3P3E.						
:100MA.MAKER:LS OR EQUAL						
RYM201000317	004	2010/03/19	M02	M0200BK-119	EA	3.0000
MR201003180006		<u>2010/03/25</u>				
****. BREAKER,EBS 103b.460V 75A. :AC460V 25KA.3 3W.3P3E.						
:100MA.MAKER:LS OR EQUAL						
*** LAST ITEM ***						
: 2010 03 22 16:00						

: